

TWIN ISLAND COMMUNITY water system ID# 41- 00265

recently completed a service line inventory to determine the type of material (e.g., copper, galvanized steel, etc.) used in service lines for all of our customers. Service lines are the smaller pipes that are used to deliver water from the larger main waterlines under the street to your home or business.). The methods we used include using historical records and meter uncovering's to determine the line material. We used the state approved statistical approach method to complete your service line inventory.

There were no lead service lines found during the development of this inventory. If you have questions about this inventory or would like a copy of the inventory, you may call Hiland Water at 503-554-8333 Ext. 107.